## **RMY Boom Angle - PV**

Recall setting 'ZN' on boom worked ok.

Boom Angle setup: BD359 as I recall....need to confirm KK's reading when he shot it.

Confirmed readings consistent with observed conditions, and manually rotating vane while mast was lowered.