

Rlw.in 'fixed'

3June06 ~10:30MDT

Rlw.in had been bad. Found loose ground wire on the excitation line. Twiddled/secured wires. Now working

Rlw.in Rpile reading ~ -20w/m2 with voltage ~ .2mV

Rlw.out Rpile reading ~ 20w/m2 with voltage ~ .2mV