

Rlw.in fixed

For two periods of an hour or more today, Rpile.in.mfs went to zero.

After trying to reseal connectors/wires in the logger box, the fix was simply to cut and restrip the wires inside the logger for the 2L/2H inputs.