

RH.2m still bad

TRH015, installed at 2m on Aug 12 18:51 UTC also reports incorrect humidities. Its cutoff is around 45%. Above 45% the reported humidity is anti-correlated with the 4 other sensors - looking more like a temperature.

In this plot, the night of Aug 11-12 shows the problem with unit 013, and the next night shows the problem with 015: