

Status 1/10

Misc stuff today

- cleaned up base a bit more
- Give Isabel a tour of satellite sites:
 - DC: took soil core; took photos; shot boom angle
 - LC: took soil core; took photos; shot boom angle
 - UP: took soil core; took photos; shot boom angle
 - PC: took photos; shot boom angle; reseated Tsoil sensor side Binder connector (preventative from a few days ago)
 - MH: took photos; shot boom angles
- Lowered DCS TT to replace 7m thermocouple, which turned out to be okay (just poor connection in logger box, down from about 1440-1650.
- Isabel rebooted cc, which brought the HRXL back to life.