

The reason why 1m.uw is now bad

As Danny sent yesterday, the 1m.uw sonic (on the right, actually mounted at 2m) is now completely buried. The sonic to the left is the disconnected sonic from 1m.c.

The TRH 1m.c also appears now to have its inlet in the snowpack.

