

sensor issues

Here is a list of what I know about sensors at each site:

Site	Battery & Solar	Sonic	Krypton	Baro	TRH	Rad	Soil	Soil.aux	Precip	Shadowband	Prop
1	ok	head off	not installed	ok	not installed	Rsw.in a bit strange, but went to 0 when covered	ok	ok	not planned	SPN1 reporting 0 Licor not working	ok
2	ok	ok	not installed	ok	not installed	Rsw.in<Rsw.out	ok	not planned	not planned	not planned	not planned
3	charging?	ok	<5mV	ok	not installed	ok	turned off?	not planned	no fluid	not planned	not planned
4	ok	ok	not installed	ok	not installed	ok	Qsoil bit high	not planned	reporting all 0	not planned	not planned
5	ok	ok	<5mV	ok	problem -1 <T<0	Rsw.in high by x2 until 11 /14 Rsw.out high by x4 Rlw.in/Rlw.out swapped	Qsoil started being erratic on 11/13	Tsoil.4.4cm bad Qsoil erratic Gsoil had spike 11/13, otherwise ok TP01 not reporting	not planned	not planned	not planned
6	ok	ok	<5mV	ok	not installed	turned off?	turned off?	turned off?	no fluid	not planned	ok
7	ok	ok	<5mV	ok	problem -1 <T<0	ok	ok	not planned	not planned	ok	not planned