

abc2 site visit

Nov 16, 14:30 MST

Per phone conversation with John.

On site Ling, John, Kurt.

Communications to this site went out last night, which appears to be due to the USB modem not being fully plugged into the router. USB light was off on the router. After pushing the modem in, comms were re-established.

Updated coefficients in down-looking pyranometer.

Tsoil died at this site at around the same time as the modem went out last night. The Tsoil probe was removed for repair.

No TRH (or krypton) at this site at this time. Everything else looks OK. Cellular levels look good here: around 60% of full signal.