

# river7 site visit

9 Jan: Oncley, Dong, Militzer

~1220: clean radiometers (including SPN1)

1225-1245: plugging/unplugging sensors to determine reason for pyg.in failure. Second plug/unplug and white-button reset fixed. Hmmm...

1245: declared "fixed"