

site wvally4 visit

12 Jan, 2011 on site: John and Ling

1520 to 1540

1525 turn off wifi

1530 add insulation to keep batteries warm. All terminal lugs were snug.

Nots:

checked radiometers. all clean

The ETI rain gauge has less fluid than when we were here Sunday so it drained some of its contents. The slurry appears to have plenty of antifreeze.