

hiland3 site visit

14 Jan: Militer, Oncley

Purpose: radiometers were covered earlier, want to check that all is well; also check ETI

Excellent snowball snow (unconfirmed) -- grass clear of snow for part of walk to station.

1346: ETI gauge all liquid; no fluid needed or added

1348-1350: A few drops of water on Rsw.in and water in Rlw.out shield, but otherwise fine. Wipe-off radiometers with residual water. All dessicants nice and blue.