

abc2 site visit, jan 16

16 Jan: Oncley&Militizer

Purpose: preemptive coating of TRH; krypton klean

1015: swap TRH with coated/greased sensor. 24 replaces 21

1019: mast down

1020: klean krypton, first time 1.3V;

1022: sprinkles just started

All mast bolts needed to be tightened (lowest section especially)!

1023: second kleaning 1.0V

1025: third kleaning. 1.1V

1032: mast up

1036-1040: replace dessicant in Rlw.in; wipe off incomings

forgot to take photos, but is raining.