

Feb 1 Riverton7, shadowband

8:30 - 9:00

Clear and very cold with high winds

Re-installed shadowband with modifications. We still suffer from sunshine when the unit is set to the correct elevation angle.

Tom lowered the licor in the mounting block such that the top of the sensor is in line with the pivot axis of the block.

Now we are getting shading at the correct angle.