

Station 2 Site Visit, February 4

10:30 cleaned radiometers

Steve tried, unsuccessfully, to reprogram the router

Update: 14:15-14:40

After testing the cables in the base came back to 2 to reprogram router. This time it was successful

It did a long time after the router reboot to be recognized as isfs2.