

Feb 5 Eslope5, TRH

10:00 - 10:30

Overcast

SHT went back yesterday. Pulled sensor and found corrosion on the sensor pins. used the special contact goop and re-installeed. Working ok.

10:21 - radiometer domes cleaned