

Fiddling with NCAR4 sonic

To check whether the krypton noise is sonic related, I've been doing some tests, changing the sonic data rate.

As of 10:42, it is now set to A9 (10sps). I'll leave this running for a few minutes to allow me to go back and look at the data.

10:50 set back to Ac (20sps).

(It looked like the winds were bad for this time period, so I didn't think much data would be lost.)

P.S. The data that I captured appear to have 2Hz noise in both configurations.