

Pressure1 down

After getting the wireless link from downwind2 and profile going this morning we did not realize that pressure1 was also down. It was restarted late this afternoon.

Note by Gordon: this system was still configured to use dhcp - and it lost its lease when the etherants were down. Fixed.