

Licors needed power cycle

Both v06 and v07 licors were down this morning. Both responded to pio cycles. v07 needed the same power cycle yesterday, however we decided that this wasn't a function of power (since these are both line-powered) and there was no correlation between crashes and Vdsm. So...we have a mystery.

update: DSM at V06 was not grounded. Will monitor Licor to see if this fixes the problem. At V07 the Licor goes through the top DSM which is not grounded. If V06 stays up then we will try grounding at V07t.

15:10 - had to restart the Licor on V06 using PIO.