

TRH work 17 May

INEGI provided climbers to replace TRHs on the tall masts today. Andy was their ground support/check. We had a bunch, all have been replaced by "bypassed" sensors:

- tnw07.60m
- tnw10.40m
- tse04.40m
- tse04.60m
- tse13.60m
- rsw03.40m

I have put BYPASS sensor types in the .xml, though we may now need make a time-varying .xml (using configs.xml)...