

RSW06 TRH.60m restarted

14:20 RSW06 TRH.60m went down again due to high current. I reset the max current to 150ma.