

## Later in the day

Spent the rest of the day at tnw02. Got everything up except the 2m sonic (because we left its boom at the ops center). However, rain (again) drove us out, so I mis-plugged sensors in. Since some involve 422 jumpers, I can't just change the config from here. We'll need another trip (tomorrow).