

Sensor issues 21 May AM

tse05: NR01 died sometime yesterday. pio doesn't work. Will need another hike to the ladder.

tse06: 2m TRH still dead – suspect fuse blown. INEGI hopefully will climb to 30m when they are here on Tues.

rne06: LiCor died, pio restarted

v06: LiCor died, pio restarted (our crontab should have restarted within 4 hours anyway)