

## **moved 7m sonic**

We noticed that a guy wire was rubbing on the bottom of the 7m sonic array, so we moved it up by about 4-5cm. In the process, we tightened the setscrew which pitched the array up a bit. This was done at 0941.