

Site Visit 08152012

August 15, 2012

10:30am - 3:00pm

Putting freshly calibrated sonics (CSATs) on turbulence tower with Licors, TRHs and barometer. The four-component radiation did not get mounted due to a mount missing. System was check with just a charger powering instruments but then shut off due to missing batteries. Everything looks good but the 2m sonic.

Guy tensions were checked.

Remember: Batteries, radiation mounting plate, radiation instrument, boom and electronics box.

45m: CSAT0537, Licor 1166

30m: CSAT0853

15m: CSAT0539, Licor 1164

7m: CSAT0800

2m: CSAT0855, Licor 0813