

updated todos

Here is my current list -- not <too> long, but some serious:

A3 add barometer (since short one, might steal C20's)

A6 add CSAT (still at CSI?)

A8 barometer not mounted at correct height -- Jielun may do using level or theodolite.

A12 sonic can't acquire signal; head ok, connector ok, power ok, cable ok

A17 sonic can't acquire signal; head ok, connector ok, power ok, cable ok

A19 sonic back in Boulder since loose head

A19 GPS reports GSx messages (Gordon couldn't fix)

M21 3m sonic missing serial cable (Chris is fixing at FLAB?)

Also:

Set-up base computer; data archiving, statsproc, cockpit, WWW plots, etc.

Power, networking, space in base trailer, etc. for Christoph

Labels: