
## Restarted 2m TRH fan on 5

Gordon, Oct 7

Last night noticed from cockpit that the fan current for the 2m TRH on 5 was 0. Logged in an restarted it with a ctrl-R from rs 5 around 8:40 pm (time determined from the data).

Here's a plot of the 5 minute averages when it died:



Will look at the 1 second data to see if it ever reported a value over 50 mA.