

a8 trh cable swap

This morning, A8 was giving checksum errors. This was running through a serial port through a cable stolen from A5 last week. Just changed out this cable.