

Licor at 32 m is flaky

June 5: 11:28 - 11:49

The Licor at 32 m (SN 1164) has been intermittent since the heavy rain on the afternoon of June 1. Gordon found the "ready when off" light to be steady red. The supply voltage was only 8.04 V, while the same voltage for the Licor at 38 m read 10.8V.

Chris suggested swapping heads to further diagnose the problem.