

# Daily status, June 7

SOAS ISFS Status, June 7, 2013

32m Licor is still down. We will remove it from the tower for trouble-shooting in the base. Options are: (1) receive loaner from Licor, (2) replace with 20m Licor and add krypton hygrometer at 20m. There is a spare sonic with a serializer (SN 0537) in the base.

Rain last night and foggy this morning. More rain likely today. Everything very wet.

Sonics: 13.9m and 32m sonics still wet and not working yet.

TRH, P, p: TRH at pond not reporting; P okay.

Wind speed & direction: See sonic report; pond U,V okay.

Soil, Rainr: tb.pond not reporting

Vmote.(rad,a,b) ~ 5.9, 9.1, 11.9 V.

Radiation, Wetness: Tsfc.32m not seen on cockpit, but okay.

Tsfc.8m intermittent over past 24 hours.

h2o, co2: 32m Licor not reporting. kryptons still wet.

System (GPS, Vdsm): ok