

Licor 7500 at 32m

Licor at 32m stopped reporting again this morning.

Power cycling didn't help:

```
ssh mid
eio 9 0
eio 9 1
```

Also tried minicom, sending a BREAK (ctrl-A F) and the Outputs command. No response.

Here's the LICOR 7500 configuration for SOASI, output at 20 Hz, bandwidth 20Hz:

```
(Outputs (BW 20) (RS232 (Freq 20.0) (Baud 19200) (EOL "0A") (Labels FALSE) (DiagRec FALSE) (Ndx FALSE) (Aux
FALSE) (Cooler FALSE) (CO2Raw TRUE) (CO2D TRUE) (H2ORaw TRUE) (H2OD TRUE) (Temp TRUE) (Pres TRUE) (DiagVal
TRUE)))
(Outputs ?)
```