

Battery replaced at soil.b

8:50 - Battery replaced at soil.b. The solar charger has been disconnected from the battery. The thought is the charger may be taking more juice than we are getting from the sun. Battery went from 6.6v to 12.9v.