

Tsoil.b replaced

10:58 - Tsoil.b has been replaced with the new probe Steve O. installed yesterday. The only good signal from the old probe (Tsoil.1.9cm.a) is 0.15C lower, which indicates that the new probe is <mostly> settled in. Note that the rain this morning should have helped "heal" the soil as well.