

20m Sonic Electronics Box Adjustment

July 10, 2013

~3:45pm CDT

Re-adjusted shim I put at 20m sonic electronics box due to cable pinching. I did this before to stop low signal flags. Let's see if this works again.

The cable to the head of the sonic is too sharp when plugged into box due to the boom bracket too close. Put a biner for a spacer to keep cables from kinking.