## flr servicing

Went in with the IOP7 crew to take care of a few tasks:

- ~14:35 cleaned krypton
- also reseated the analog connectors on the krypton electronics box in an attempt to avoid the mess we saw last night
- 14:52 reoriented SPN1 back to original position (analog cable pointing north)
- ~14:54 cleaned radiometers

Then hiked to NNE, SSW1, S, SSW2, SSW3, SSW4 to take GPS positions (Sebastian did SW, WSW, W at the same time)