

visit to flr

John & Steve: 1:30-3:30. (Wind was wicked on the rim trail, but not bad on the way down. A fair amount of dust in the crater.)

flr wasn't pinging (and neither was flr lldar) as of 11AM today.

flr DSM wouldn't respond to console -- cycled power. Pocketec took a while to fsck, but then booted okay.

lidar generator had stopped (even though the gas tank was only at half). Sebastian and Eric came into the crater as well to diagnose/fix it.