

Daily Status 10-12-2016

Wet over night, 105% RH. Partly cloudy today and cool, light breeze.

To dos:

- Reshoot boom angles at S15 and others sites that previously have only had one
- Second soil core at S15? (Steve do you still want this? Gordon and I were only aware of one at S1 which was done today)
- Check out failure of S11. It's not reporting, but we don't know why.

Station Status: S11 is down.

T/RH: 42m TRH came back after being power cycled. Others okay (note that S1,2,9,10 are wired not to report lfan).

P: ok

2D Gill: ok

csat u,v: ok

csat ldiag: ok

csat w, tc: ok

3D RMY: ok

EC150: ok

motes: ok

Wetness: ok

radiation: ok

Tsoil: ok

Gsoil: ok

Qsoil: ok

Cvsoil: Ready to manually read sensor

Rainr: ok.

Vbatt: Vbatt.tower at 12.6V on 10/9