

hiland3 site visit

10:00 John just called from the site. He tested the ETI gauge with about 1/2 liter of water and saw 26 tips. 27 tips would have been exact. Thus, this gauge appears to be working.