

# site wslope6 visits

12 Jan 2011 on site: John and Ling

1425-1500

1428 turn off wiki

1430 install insulation for batteries, and add third battery

notes:

radiometers are clean.

rain gauge looks good.