

Site Visit 07-29-2011

Arrived: 10:12am MDT

Departed: 1:45pm MDT

Ned and I did a couple of chores on this visit. First, we fixed the 43M sonic. It seemed to be the port on the Emerald Card. Switched 43M sonic from port16 to port20. Ned updated the xml. Second, we replaced two 15M cable from 43M Licor with a 30M cable. When we did this we noticed interrupts on the dsm. Having unplugged the battery charger for the laptop to talk with dsm, we plugged the charger back in and the dsm didn't give as much interrupts. [shrugging] Will keep an eye on this odd situation. Third, we clean all three Licors. Fourth, took guywire tensions.

Want to mention that there is a 2M tower just 15' South of the Turbulence Tower. WTF?

Also, there are no more ports on ethernet switch or 120AC power.