

Soil Installations

TP01 Installation Note: The sensors were placed in the ground at the proper depth, but the transducer foil was oriented 90-degrees off, being flat rather than edge facing up.

See photos for some of the soil installations taken at/prior to teardown. Note the branch at SoilB and the uncovered transducers prior to excavation. Other photos are available on the project repository and will be posted to the web page when available.



