Daily Status - 9/12/16

9/12/16

Summary: Light winds, 5 m/s, out of the NE, clear, EC150, at site #15, was down for a period yesterday (refer to blog for more information)

Actions past 24 hours:

- installed Gill 2D at site 8
- EC150 was down for short period, Oncley got it back up

To dos:

move rad/soil Mote #1 to another site, #1 or #9

Sensor Status:

T/RH: ok P: ok 2D Gill: ok csat u,v: ok csat ldiag: ok csat w, tc: ok

EC150: ok, was down for a period of time yesterday (~11:00 am to ~10:00:pm)

motes: ok Wetness: ok radiation: ok Tsoil: ok Gsoil: ok Qsoil: dk

Cvsoil: not responding

Vbatt: ok