



Daily Status 10-30-2016

Sunny morning, followed by an overcast afternoon. Steady west wind all day.

Introduced Clayton to the Marsh and visited a couple of sites.

Found S1 barometer tube had fallen of the sensor nipple, sometime between the last site visit and 12:15 today.

Bird managed to outsmart the mitigation at site 1:



T/RH: 42m TRH reporting warmer and drier than at other levels.

P: ok

2D Gill: ok

csat u,v: ok

csat ldiag: ok

csat w, tc: ok

3D RMY: ok

EC150: ok

motes: ok

Wetness: ok

radiation: ok

Tsoil: ok

Gsoil: ok

Qsoil: Qsoil.5cm.s9 reporting intermittently

Cvsoil: ok

Rainr: ok.

Vbatt: ok