

Cleaned radiometers and solar panels

November 30, 2010

Site 2 (ABC): upper radiometers snow/ice covered; lower pyrgometer has a little frost on it; cleaned

Site 3 (Highland): upper radiometers partially snow/ice covered; cleaned @ 11:20

Site 1 (Playa): Radiometers bare of snow

Site 7 (Riverton): Radiometers bare of snow

Site 5 (E slope): cleaned uplooking radiometers @ 14:53

Cleaned solar panels as needed at all these sites; mostly bare or a little snow/ice near the bottom