

# eslope5 krypton, soil

Dec 11, 5:10 pm, Tom, Gordon

Tom installed old-style single soil probe at main soil site, unit 23

mast down 5:15, cleaned krypton, mast up 5:27. Sonic wicks ok.

twh (3/1/11): high-rate w suggests mast down 17:17 - 17:26

(3/2/11): high-rate u, P indicate mast down 17:16 - 17:27

high-rate kh2oV indicates kh2o cleaned at 17:20

Inserted GPS jumpers in main soil mote.