

river7 site visit, Jan 6, 2011

6 Jan Dong&Oncley

5--10cm of hard wind-packed snow

1140 install a new radiometer (twh: SPN1)

1138 clean up radiometers

1140 soil sample

1147 take pictures

boom angles: 86.6 (looking up) 85.6 (to tower near tripod)

TRH fan okay