

eslope5 site visit, jan 17

17 Jan: Miltzer&Oncley

Purpose: coat TRH; soil core

Conditions: mostly overcast, calm, snow is melting fast here with perhaps 50% grass/soil exposed.

Radiometer dessicant okay -- no other action taken.

1110: TRH 18 removed for coating. The probe connector had been greased previously. There was some green corrosion on the transducer pins. Cleaned with methanol and coated with nail polish before re-installation.

1120 MainSoil core sample taken (containers 3)

1132 AuxSoil core sample taken (containers 4)

Decided against Kh2o cleaning since yesterday it was at ~2.5v and there has been rain intermittently. Currently at ~.3v

Decided against taking additional photos at this time because many have been taken here.