

river7 site visit

Jan 17: Militzer&Oncley

Purpose: coat TRH; soil core

Conditions: Cirrus overcast; broken altoCu; only patches of snow left (20%?)

TRH looked good. Added some nail polish and reinstalled.

1221: soil core taken (containers 5)

Added 3rd battery (just for giggles). Should get a bunch of charging today.

1245: (radically) adjusted shadow band. (Angle changed from 38->52 degrees