

abc2 site visit, jan 18

18 Jan: Militzer&Oncley

Purpose: clean krypton (hasn't been good for a while, despite methanol cleaning not long ago); NESW photos

Conditions: frosty, broken cirrus, great visibility

found honey bottle (without cap)

NESW photos taken

0810: mast down

0814: klean krypton with methanol 0.1 -> 1.7

0816-0818: klean krypton with distilled 0.0->1.7

0821: replace Rsw.in dessicant

0828: soil core taken

0829: mast up

0835: realized that barometer line was disconnected from barometer nipple. reconnected