

Jan 27 Site visit Eslope5

14:15 - 15:15

Clear day, 50% snow cover on ground.

14:23 SHT018 replaced with SHT009

14:28 Mast lowered

14:31 cleaned krypton with water (1.6v to 2.35v), retracted sonic wicks, checked tower bolts, soil sample taken at main site

14:50 raised mast

14:55 cleaned radiometer domes with water, soil sample at secondary site, sample depths backwards in tupperware

13:14 pounded tower stakes in